

Steve Hahn CDF Meeting 04/03/2003

				Dolivered	Livo			Cood Bun	Runs Taken
Store	Start	Stop	Hours	Delivered Luminosity	Live Luminosity	Efficiency	Good Run	Good Run with Silicon	During Store
Store			110015	Luminosity	Luminosity	Efficiency	Good Rull	WILL SHICOLL	
		2003.03.28-							160659
<u>2361</u>	18:37	07:39	13.0	591.7	527.1	89.1%	527.1	527.1	160663
	2003.03.29-	2003.03.30-							160742
<u>2370</u>	11:47	07:20	19.6	1211.0	699.6	57.8%	682.8	682.8	160761
									160796
									160797
	2003.03.31-	2003.03.31-							160798
<u>2375</u>	01:25	12:50	11.4	575.2	483.2	84.0%	433.1	433.1	160802
	2003.03.31-	2003.04.01-							
2377	15:51	07:52	16.0	1008.6	924.3	91.6%	924.3	924.3	160823
									160887
									160890
									160891
									160892
									160894
	2003.04.02-	2003.04.03-							160895
2385	10:58	09:35	22.6	1511.4	1184.4	78.4%	986.0	986.0	160896




Steve Hahn CDF Meeting 04/03/2003

- Thursday-Friday:
 - > Store 2361
 - In at 1830 @ initial lum = 1.8×10^{31} .
 - Lost some efficiency to TOF threshold studies.
 - Beam lost due to D0 low-β quad; only CMX trip at CDF.

Friday:

- Access from 0800 to 1000 to work on muons calorimeter TDCs.
- Power outage at 1030—due to uninterruptable power supply interruption—to APACS chassis generated every alarm in MCS bringing down all detector, HV and rack power. Many APACS modules required multiple reboots to come back to life. DAQ was usable at 1600.
- Lingering problems through weekend and even Monday. Running solenoid using the accelerator helium header instead of our compressor. We accessed from 1630 to 1800 to fix TSU BSU SVX. Coincidentally, D0 had calorimeter preamp fan problem which put them in access until 2300.



Monitoring ace's worst nightmare



Steve Hahn CDF Meeting 04/03/2003

- Saturday-Sunday:
 - Beam studies Sat owl for damper and coalescing problems.
 - > Store 2370:
 - Magnet was still not fully up when beam was in.
 - High loss: ~3hour before Si in
 - High muon trigger rate (power cycled crate)

Sunday:

- > Store 2372
 - Initial lum = 0.5×10^{30} when pbars mostly lost due to seperator spark.
 - Following studies could not reproduce this problem
 - Store in only 1/2 hour

Monday:

- Store 2375
 - Initial lum = 20.5×10^{30} (not bad for stack = 100 mA)
 - Smooth data taking with Si
 - End of store Trigger table tests (L3 SVX, L2 DPS)



Steve Hahn CDF Meeting 04/03/2003

- Monday-Tuesday:
 - Store 2377
 - Initial lum = 20.5×1030 (not bad for staxk = 100 mA)
 - Smooth data taking with Si
 - >90% store efficiency (no Tests)
- Tuesday:
 - > 24 hours of "maintenance" shifts starting at 0800 to smooth beam orbits.
 - After switching solenoid back to our compressor, solenoid fast dumped while ramping up. Called Rob back from fishing, found that evening bad dump chassis. Bad relays replaced Wednesday morning and magnet ramped up.
- Wednesday-Thursday:
 - > Store 2385.
 - Was to be dropped at 0600, but linac to booster protons down by 2X.
 - "Paraphase curve module" swapped out.
 - Done XFT, XTRP, and trigger studies while this was fixed till 1100.